

Oil Field Environmental Incident Summary

Incident: 20140707124531 **Date/Time of Notice:** 07/07/2014 12:45

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: EVELYN 33-25NH

Field Name: CEDAR HILLS

Well File #: 17534

Date Incident: 7/7/2014

Time Incident: 06:00

Facility ID Number:

County: BOWMAN

Twp: 132

Rng: 107

Sec: 25

Qtr:

Location Description:

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels	25	Barrels	25	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/29/2016

Clean Up Concluded: 7/14/2014

Risk Evaluation:

None

Areal Extent:

5 ft x 10 ft

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

Standing fluid was sucked up and contaminated material will be removed.

Wastes Disposal Location: Petrocomp

Agencies Involved:

Updates

Date: 7/7/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking, according to the report.
NDIC retains oversight.